



BOLZANO Natural Leather



Technical Specifications

Leather Type	Bovine
Origin	European And Non-European
Thickness	0.9–1.00± 0.1 mm
Average Hide Area	4 - 4.5 sqm
Tannage	Chrome Salts
Dye	Aniline Dye
Finishing	Mixture Of Oils, Waxes & Polurethane Ecological
Appearance	Natural Grain With Pull Up Effect
Colour Fastness to Dry Rubbing 50 Cycles UNI EN ISO 11640 · UNI EN ISO 11641	Grey Scale 3
Colour Fastness to Wet Rubbing 50 Cycles UNI EN ISO 11640 · UNI EN ISO 11641	Grey Scale 3
Colour Fastness to Alkaline Sweat 20 Cycles UNI EN ISO 11640 · UNI EN ISO 11641	Grey Scale 3
pH UNI EN ISO 4045	3.5
Tear Strength UNI EN ISO 3377-1	20 N
Colour Fastness to Light Xenotest ISO 105 B02	Blue Scale 3

Applications & Features



REACH Compliant · Respects the Environment

Respects the environment through application of new technologies in the production process

Clean and Care

- Dust regularly with a soft, dry cloth to keep the surface clean.
- Clean occasionally with a slightly damp cloth using a neutral, non-detergent soap; wipe dry immediately.
- Avoid solvents, detergents, bleach and abrasive cleaners. Keep away from direct heat sources and prolonged sunlight.
- Treat premium leathers periodically with a suitable leather conditioner.

All submitted test results are obtained using official methods on non-manipulated leather. Natural markings, healed scars, wrinkles and grain or shade variations are inherent characteristics of genuine leather and are not considered defects. We reserve the right to modify, at any moment and without notice, any product specifications.



WIPE



NO BLEACH



DRY



NO IRON



NO SOAK

